





TSB-203 042026 Rolling Bridge Jack In-Field Bolt Replacement



Rolling Bridge Jack w/
incorrect, **short** cinch
bolts in 4 locations



01

Remove **short** cinch
bolt, retaining cinch nut
for immediate re-use

02

Replace with **new**,
proper length cinch bolt,
replacing cinch nut

03

Seat **new** cinch bolt so
that it correctly bears on
arm to cinch.

WARNING! (Yes... even on a document *this* small, there is **still** fine print - **read** it please!)

ALWAYS make sure rollers are properly positioned on runway utility rails and all ADJUSTMENT (CINCH) BOLTS are tightened before use or serious injury may result. READ PRODUCT MANUAL BEFORE USING THIS JACK.